


# Isabella County

## 2018 & 2019 Road Surface Ratings



### Legend

### 2018 & 2019 Isabella Paser Ratings Surface Rating

- 1 - 4 Structural Improvements
- 5 - 7 Capital Preventative Maintenance
- 8 - 10 Routine Maintenance

**Total PASER Miles: 411.673**

### A Cooperative Effort Between:

- Isabella County Road Commission
- Michigan Department of Transportation
- East Michigan Council of Governments
- Transportation Asset Management Co

**East Michigan Council of Governments**  
 3144 Davenport Ave. Suite 200  
 Saginaw, MI 48602  
 989-797-0800 Fax 989-797-0896  
[www.emcog.org](http://www.emcog.org)



Created 12/02/2019

